





- ⚡ Look for frayed welding leads and any damage to the welder.
- ⚡ Ground the welder case.
- ⚡ Use mats of plywood, rubber, or some other dry insulation to stand or lie on.
- ⚡ Wear dry gloves in good condition and other personal protective equipment when welding.