©2023, CPWR-The Center for Construction Research and Training. All rights reserved. CPWR is the research and training arm of NABTU. Production of this document was supported by cooperative agreement OH 009762 from the National Institute for Occupational Safety and Health (NIOSH). The contents are solely the responsibility of the authors and do not necessarily represent the official views of NIOSH.

Falls: An Interdisciplinary Annotated Bibliography

Ahn, C. R., et al. (2019). "Wearable Sensing Technology Applications in Construction Safety and Health." Journal of Construction Engineering and Management 145(11): 03119007.

The advent of wearable sensing technologies has produced unprecedented opportunities for the near real-time collection and analysis of workers' safety and health data. To encourage

(25.5%). However, the conditions with the longest disability durations were sudden-onset injuries, including fractures of the ankle (median = 55 days), foot (42 days), and wrist (38 days). Same-level and elevated falls were the principal exposures for fractures of the wrist and ankle, whereas elevated falls and struck by incidents accounted for a majority of foot fractures. Manual materials handling activities were most often associated with low back pain disability. The results suggest that these most disabling injuries can be addressed by increasing primary prevention resources in slips and falls and exposures related to injuries of sudden-onset as well as in reducing manual materials handling and other exposures associated with more gradual-onset injuries.

Cruz, Y., et al. (2018). "Characterization of Foreign-Born vs. Native-Born Worker Fatalities in Kentucky, 2001-2014." J Immigr Minor Health 20(2): 448-455.

Information on foreign-born worker (FBW) and native-born worker (NBW) fatal injuries is scarce. The Kentucky Fatality Assessment and Control Evaluation program analyzed 2001-2014 worker fatality data. The Kentucky FBW fatality rate was double the US FBW and NBW rates, and 50% higher than the Kentucky NBW fatality rate. FBW average age at death was 38 years; NBW age was 47 years. FBW deaths occurred in construction (26%) and services (22%) industries, and transportation [28% (54% due to semi truck crashes)] and construction [26%(48% due to roofing, scaffolding, and ladder-related falls)] occupations; in contrast, NBW deaths occurred in services (22%), and transportation (18%) industries, and transportation (25%) and management (20%) occupations, and were due to exposures to inanimate mechanical forces (38%), and transport accidents (30%). Enhanced FBW cultural competent interventions and policies are needed to prevent FBW occupational injuries and improve FBW workplace safety and health.

Cutlip, R., et al. (2000). "A comparison of different postures for scaffold erection and disassembly." Appl Ergon 31(5): 507-513.

Overexertion and fall injuries comprise the largest category of nonfatal injuries among scaffold workers. This study was conducted to evaluate the effects of scaffold height (2.8 m, 5.8 m, 8.8 m, 11.8 m) and work posture (free style, stoop, kneel, squat) on the biomechanical loading of the lower back during simulated scaffold erection and disassembly tasks. Ten experienced male scaffold workers participated in the study. Each subject performed a scaffold erection and disassembly task at each of the four scaffold heights using each of the four postures. Three-dimensional kinematic data were collected using a video motion analysis system. Kinetic data were collected using force platforms. Peak and cumulative L5/S1 moments were calculated using a three-dimensional biomechanical model. Peak and cumulative L5/S1 moments were significantly affected by scaffold height and work posture. Peak moments were highest at the 11.8 m scaffold height and lowest at the 2.8 m height. Peak moments were highest for the squat posture and lowest for the kneel posture. Cumulative moments were highest for the stoop posture and lowest for the kneel posture. Cumulative

information to guide prevent

(25.5%). However, the conditions with the longest disability durations were sudden-onset injuries, including fractures of the ankle (median = 55 days), foot (42 days), and wrist (38 days). Same-level and elevated falls were the principal exposures for fractures of the wrist and ankle, whereas elevated falls and struck by incidents accounted for the majority of foot fractures. Manual materials handling activities were most often associated with low back pain disability. The results suggest that these most disabling injuries can be addressed by increasing primary prevention resources in slips and falls and exposures related to injuries of sudden-onset as well as in reducing manual materials handling and other exposures associated with more gradual-onset injuries.

Cruz, Y., et al. (2018). "Characterization of Foreign-Born vs. Native-Born Worker Fatalities in Kentucky, 2001-2014." J Immigr Minor Health 20(2): 448-455.

Information on foreign-born worker (FBW) and native-born worker (NBW) fatal injuries is scarce. The Kentucky Fatality Assessment and Control Evaluation program analyzed 2001-2014 worker fatality data. The Kentucky FBW fatality rate was double the US FBW and NBW rates, and 50% higher than the Kentucky NBW fatality rate. FBW average age at death was 38 years; NBW age was 47 years. FBW deaths occurred in construction (26%) and services (22%) industries, and transportation [28% (54% due to semi truck crashes)] and construction [26%(48% due to roofing, scaffolding, and ladder-related falls)] occupations; in contrast, NBW deaths occurred in services (22%), and transportation (18%) industries, and transportation (25%) and management (20%) occupations, and were due to exposures to inanimate mechanical forces (38%), and transport accidents (30%). Enhanced FBW cultural competent interventions and policies are needed to prevent FBW occupational injuries, and improve FBW workplace safety and health.

Cutlip, R., et al. (2000). "A comparison of different postures for scaffold end-frame disassembly." Appl Ergon 31(5): 507-513.

Overexertion and fall injuries comprise the largest category of nonfatal injuries among scaffold workers. This study was conducted to [illegible]

with best practices guidelines for portable ladder use designed for applications in the construction industry. Implemented on a hand-held computer, the assessment tool consisted of a series of checklists categorized in four groups; ladder condition, setup, moving on a ladder, and completing tasks from a ladder. For these four observational categories, the resulting tool contained 31 and 33 questions for step and extension ladders, respectively. Three individuals trained to use the tool scored a set of photographs and videos depicting 25 ladder conditions, 20 ladder setups, 10 users moving on ladders, and 13 users completing tasks from a ladder for a total of 78 observations. The assessment tool had good agreement across and within raters. For the three raters, agreement ranged from 79% to 97% across the questions. Within one subject, kappa coefficients for the intrarater reliability ranged from 0.67 to 0.91. The tool offers a practical method to quantify best practices associated with ladder use that can ultimately inform targeted intervention efforts.

DiDomenico, A., et al. (2010). "Effects of simulated occupational task parameters on balance." Appl Ergon 41(3): 484-489.

The effects of single-handed load holding, length of the base of support, and standing surface condition (narrow and wide construction beams) on balance were investigated in twenty-three healthy men between the ages of 18 and 55 years old. Balance during quiet standing was evaluated from postural sway measurements derived from center of pressure (COP) displacement. These measurements included the range or maximal displacement of the COP in the anteroposterior (AP) and mediolateral (ML) directions, the elliptical area, and mean sway velocity. Holding a load in the hand did not significantly affect postural sway measures ($p > 0.05$), although the effect of surface condition was significant on all COP measures ($p < 0.001$). Lengthening the base of support did not affect the ranges or elliptical area, but increased the mean velocity of sway ($p = 0.001$). Changes in the dimensional characteristics of the surface condition and length of base of support affected postural sway, possibly by requiring adjustments to balance and motor control strategies. Further research is required to determine if these changes are detrimental to maintaining balance and increase the risk of falls for workers in similar environments.

DiDomenico, A., et al. (2010). "Perceptions of postural stability after transitioning to standing among construction workers." Safety science 48(2): 166-172.

Falls are a leading cause of fatal and nonfatal injuries in the construction trades. This study explored construction workers' self-reports of postural stability upon standing after working in different postures. One hundred and eighty-nine workers in 10 construction trades provided stability ratings by completing a written questionnaire. Additional data collected included age, gender, years of experience, and rating of overall balance. Construction workers rated their overall balance as high, furthermore, no difference was found between trades or age groups. Significant differences in stability ratings were provided for the various postures. The most commonly used non-erect postures (bent over at waist, squatting, and forward kneeling) resulted in the largest self-reports of instability. Sitting on elevated surface and sitting on level surface resulted in the highest levels of self-reported stability and are recommended when maintaining balance is a concern. Differences associated with construction trade and age were also found, but were thought to be attributed to differences in tasks performed since no differences were found when each posture was analyzed separately. The results suggest that the working posture used to complete a task affects the postural stability upon standing regardless

Population Survey. The demographics and characteristics of fatal falls among Hispanic workers were examined and compared with that of their white, non-Hispanic counterparts. The results show that fatal injuries among Hispanic construction workers were more likely to be caused by a fall than their white, non-Hispanic counterparts (OR=1.48, 95% CI: 1.05-2.10) after controlling for possible confounders. The rate of fatal falls for foreign-born Hispanic construction workers was 5.5 per 100,000 FTE, which is significantly higher than 4.1 per 100,000 FTE for Hispanic workers who were born in the U.S. (OR=1.36, 95% CI: 1.08-1.67). The disparities in fatal injuries from falls were found in age groups, job tenure, occupations, and types of construction projects. This study also found that about every two of three fatal falls in construction occurred in establishments with 10 or fewer employees. More prevention, intervention, and training measures must be applied to Hispanic workers, especially those who are new immigrants. OSHA enforcements should target small construction establishments in order to lower overall fatality rates, costs, and unnecessary losses of life.

Dong, X. S., et al. (2017). "Fatal falls and PFAS use in the construction industry: Findings from the NIOSH FACE reports." Accid Anal Prev 102: 136-143.

This study analyzed the Construction FACE Database (CFD), a quantitative database developed from reports of the Fatality Assessment and Control Evaluation (FACE) program conducted by the National Institute for Occupational Safety and Health (NIOSH). The CFD contains detailed data on 768 fatalities in the construction industry reported by NIOSH and individual states from 1982 through June 30, 2015. The results show that falls accounted for 42% (325) of the 768 fatalities included in the CFD. Personal fall arrest systems (PFAS) were not available to more than half of the fall decedents (54%); nearly one in four fall decedents (23%) had access to PFAS, but were not using it at the time of the fall. Lack of access to PFAS was particularly high among residential building contracdi

T[(42%)3stry rrt-2 (ng i)-qu2 (di)-2 (ng i)-ontr)-2 (i)-2 (ona)4 Oit

Dong, X. S., et al. (2012). "Fatal falls among older construction workers." Hum Factors 54(3): 303-315.

OBJECTIVE: This study examines recent trends and patterns in fall fatalities in the U.S. construction industry to determine whether fatal falls among older workers are different from younger workers in this industry. BACKGROUND: Falls are the leading cause of fatalities in

Apprentices working residential construction were more likely to fall from heights (OR = 2.26, 95% CI 1.59–3.21) than those working commercial construction. The revised training resulted in improved fall safety knowledge, self-reported worksite behaviors, risk perceptions, and safety climate, even after adjusting for temporal trends. We also observed significant improvements in fall safety compliance in most domains of the worksite audit, with larger changes observed in areas emphasized in the training, demonstrating specificity of the effect. Greater effects were noted in small and medium-sized contractors, who often have limited resources to devote to safety. Self-reported falls fell from 18.2 to 14.5 per 100 person-years of work. This research supports growing evidence that worksite safety can be improved by training. This curriculum could be readily adapted to other union apprenticeship programs. Fall safety of inexperienced residential construction workers' should remain a focus of future research. © 2016 Elsevier Ltd

Evanoff, B., et al. (2012). "Outcomes of a revised apprentice carpenter fall prevention training curriculum." Work 41 Suppl 1: 3806-3808.

Falls from heights are a leading cause of morbidity and mortality among construction workers, especially inexperienced workers and those performing residential construction. This research reports changes irsl 2 (c)4(h r)-7 (e)42 (e)4 (d c)4 (onth)-10 o(nge)4 (s)-1uppo irucl adiarpente( )-10 (i

subjects (aged 25-35 years) on inclined and level surfaces using embedded force plates and an Inertial Measurement Unit (IMU). Four 90-second trials were collected on the inclined surface in distinctive positions: (1) Toes raised 20° above heel; (2) Heels raised 20° above toes (3); Transverse direction with dominant foot inverted at a lower height; (4) Transverse direction with non-dominant foot inverted at a lower height. Limit of Stability was evaluated by the two measurement devices in all four directions and margin of safety was quantified for each individual on both surfaces. The results reveal significant differences in postural stability between the flat surface condition and the inclined surface condition when subject was positioned perpendicular to the surface slope with one foot descended below the other; specifically, a significant increase was identified when visual support was interrupted. The findings lend support to the literature and will assist in future research regarding early detection of postural imbalance and preventative measures to reduce fall risks in professions where workers are consistently exposed to inclined surfaces. © 2013.

Grant, A. and J. Hinze (21jEM((e)4 k( )TjEM1-2 (a)4 (r)-8.21 -1.1)-2 (e)4 (t.15 Td[(i (i)-2 (on w)2 (he) (i)-2 (or

possultsambady (duc)4 (e)(nt)-2m2 (f)m0 (a)4 (nd d4 ( )-10 (2e)h]T42 (y)]T 2013.)u (i)-2h10 (a)4 (n [(a)-[((duc
omf

Hatipkarasulu, Y. (2010). "Project level analysis of special trade contractor fatalities using accident investigation reports." J Safety Res 41(5): 451-457.

INTRODUCTION: Construction is among the most dangerous industries in the United States accounting for thousands of fatalities every year. Although there is data available on high risk work types and areas, the project-

the ability to identify individual truss/bracing element failures, and the measurement of individual member deflection. © 2016 American Society of Civil Engineers.

Hsiao, H., et al. (2005). "Human responses to augmented virtual scaffolding models." Ergonomics 48(10): 1223-1242.

This study investigated the effect of adding real planks, in virtual scaffolding models of elevation, on human performance in a surround-screen virtual reality (SSVR) system. Twenty-four construction workers and 24 inexperienced controls performed walking tasks on real and virtual planks at three virtual heights (0, 6 m, 12 m) and two scaffolding-platform-width conditions (30, 60 cm). Gait patterns, walking instability measurements and cardiovascular reactivity were assessed. The results showed differences in human responses to real vs. virtual planks in walking patterns, instability score and heart-rate inter-beat intervals; it appeared that adding real planks in the SSVR virtual scaffolding model enhanced the quality of SSVR as a human - environment interface research tool. In addition, there were significant differences in performance between construction workers and the control group. The inexperienced participants were more unstable as compared to construction workers. Both groups increased their stride length with repetitions of the task, indicating a possibly confidence- or habit-related learning eff[(t)-2 i40 (ng e)-6 (f)23 (f)(-12 (i5 (a))3 (di)l (e)4 (r)3 (e)4 (d y s)-1 (c)4 -2 (ng a)4 (pos)-1 (s-2 (he)4

postural stability observed while conducting the same activities on a forceplate (F-COPv). The experiment evaluated stationary-posture tasks with various fall-risk profiles: standing and squatting in different situations (e.g. wearing a loaded harness with a symmetric and an asymmetric load, and holding a toolbox). The analysis's results demonstrated a significant difference in I-COPv and rAcc values across different postures and tasks and also showed considerable correlations between the metrics from both the force plate and the IMU sensors. The results showed the distinguishing power of I-COPv and rAcc in measuring the fall risk of different construction workers' tasks in the stationary posture. © 2015 Elsevier Ltd.

Jensen, R. C. and C. J. Holland (2020). "Ladder Safety: A Taxonomy of Limb-Movement Patterns for Three Points of Control." Int J Environ Res Public Health 17(8).

Traditional guidance on ladder safety emphasizes training workers on the use of three points of contact. More recent guidance is to train workers to use three points of control. What is lacking is empirical information about what limb-movement patterns effectively support the use of three points of control. This project was conducted to establish a taxonomy of possible limb-movement patterns and a means for comparing relative safety. Prior to the experiment, a taxonomy of six possible limb-movement patterns was established. A sample of 20 undergraduate students performed four tasks each without any instructions on limb-movement pattern. The tasks were ascending and descending a straight ladder and a portable ladder, once each, while being videotaped. Out of 80 observed tasks, 59 of the subjects were using rungs rather than rails. Analysis of rung users identified the use of all six patterns. An innovative measure of safe performance was developed and used to compare the patterns. Statistical analysis did not find significant differences in the patterns based on the safety performance measure.

Kaskutas, V. (2014). "Fall Protection Resources for New Home Construction (CPWR Report)."

Kaskutas, V., et al. (2016). "Foremen's intervention to prevent falls and increase safety communication at residential construction sites." Am J Ind Med 59(10): 823-